

Exploded view diagram of a mechanical assembly, showing various components and their assembly points. The diagram includes the following labeled parts:


- Top Left Assembly:** SK307, KA09B, KA10, KA348, KA37, SK292, SP07, KA38, KA09.
- Bottom Left Assembly:** KA06R, KA13, KA12, KA15, KA048, SK292.
- Bottom Left Assembly (Bottom):** SK261, SK257, KA27, KA29.
- Central Assembly:** SK308, KA28, KA22, KC39-5B, KA33, KA368, KA018, SK316, SK304, KA42, KA40, KA41, KA05, NK28, SK404, KB05, WK22, SW02, SK400, KA21, KA24, SK401, KA01, KA25, SK257, KA26, SK217, KB29.
- Right Side Assembly:** SK257, KB31, SK250, SK305, KA42, KA40, KA41, NK28, SK404, KB05, WK22, SW02, SK400, KA21, KA24, SK401, KA01, KA25, SK257, KA26, SK217, KB29.
- Bottom Right Assembly:** SK249, WK01, KB228, KB238, KB05, NK23, KB128, WK08, SK231, WK09, SK403.
- Legend:**
 - KB02B
 - ▲ KB01B
 - KB02B
 - ▲ KB01B

▲ PARTS FOR 3,4 THREAD MACHINE:

■ PARTS FOR 5 THREAD MACHINE.

● PARTS NUMBER IS LISTED IN CONVERSION CHART.
★ PARTS CAN ONLY BE SUPPLIED PER GROUP


PARTS LIST FOR KC KD GROUP



Special description:
 ① KD04 be used in regular clutch motor
 KD35 be used in position motor
 ② Parts for KD35 only

REMARK:
 ▲ PARTS FOR 3-4 THREAD MACHINE
 ■ PARTS FOR 5 THREAD MACHINE
 ● PARTS NUMBER IS LISTED IN CONVERSION CHART.
 ★ PARTS CAN ONLY BE SUPPLIED PER GROUP.

PARTS LIST FOR KF KG GROUP



Special description:


- ① KG01 FOR 6 THREAD.
② KG42 FOR 2, 3, 5 THREAD.
KG54 FOR 4, 6 THREAD.
③ 4KG12 FOR 4 THREAD.
5KG12 FOR 5 THREAD.
④ KG32 FOR 6 THREAD.

- ⑤ KG471 FOR 3 THREAD.
KG472 FOR 4 THREAD.

REMARK:

- ▲ PARTS FOR 3,4 THREAD MACHINE.
■ PARTS FOR 5 THREAD MACHINE.
● PARTS NUMBER IS LISTED IN CONVERSION CHART.
★ PARTS CAN ONLY BE SUPPLIED PER GROUP.

PARTS LIST FOR KJ KL GROUP



REMARK:

▲ PARTS FOR 3.4 THREAD MACHINE.

■ PARTS FOR 5 THREAD MACHINE.

● PARTS NUMBER IS LISTED IN CONVERSION CHART.

★ PARTS CAN ONLY BE SUPPLIED PER GROUP.


Special description:

① TF28 FOR 516x1. ② TF22 FOR 516x1.

③ TF26 FOR 516x1. ④ KJ51, KL30 ARE LISTED IN KC KP GROUP.

⑤ TF42 FOR 516x1.

PARTS LIST FOR KM KN GROUP



REMARK:


▲ PARTS FOR 3.4 THREAD MACHINE.

■ PARTS FOR 5 THREAD MACHINE

● PARTS NUMBER IS LISTED IN CONVERSION CHART—

PARTS NUMBER IS LISTED IN CONVERSION
+ PARTS CAN ONLY BE SUPPLIED PER GROUP


PARTS LIST FOR KP KQ GROUP



REMARK

- ▲ PARTS FOR 3.4 THREAD MACHINE.
- PARTS FOR 5 THREAD MACHINE.
- PARTS NUMBER IS LISTED IN CONVERSION CHART.
- ★ PARTS CAN ONLY BE SUPPLIED PER GROUP.

PARTS LIST FOR KR KS GROUP



REMARK:


▲ PARTS FOR 3.4 THREAD MACHINE.

■ PARTS FOR 5 THREAD MACHINE.

● PARTS NUMBER IS LISTED IN CONVERSION CHART.

★ PARTS CAN ONLY BE SUPPLIED PER GROUP.

PARTS LIST FOR KT KU GROUP




Special description:

- Special description: ① 4KU27 FOR 4 THREAD. ② 5KU27 FOR 5 THREAD. ③ 4KU23B FOR 4 THREAD. ④ 5KU23B FOR 5 THREAD.

REMARK:

- ▲ PARTS FOR 3-4 THREAD MACHINE.
■ PARTS FOR 5 THREAD MACHINE.
● PARTS NUMBER IS LISTED IN CONVERSION CHART.
★ PARTS CAN ONLY BE SUPPLIED PER GROUP.

PARTS LIST FOR KW KX KY GROUP




Special description:

3KW01B-Thread Stand Complete for 3 Thread
 4KW01B-Thread Stand Complete for 4, 5 Thread
 6KW01B-Thread Stand Complete for 6 Thread

REMARK:

- ▲ PARTS FOR 3.4 THREAD MACHINE.
- PARTS FOR 5 THREAD MACHINE.
- PARTS NUMBER IS LISTED IN CONVERSION CHART.
- ★ PARTS CAN ONLY BE SUPPLIED PER GROUP.

SPARE PARTS CONVERSION CHART

MODEL	GAUGE NG SM													
861B001-1	1.5	E934	(D290) + D438+D912	H442 H442	1.6	P152 F525	KS62	LP26	KG131	KF25 STD	KJ09B	KJ10	#9	5.5
861B001-4	4	E800	(D575) D440+D095	H445	1.6	P253 F371	KS62	LP26	KG131	KF25 STD	KJ09B	KJ10	#11	5.5
861B001-5	5	E797	(D574) D440+D674	H445	1.6	P230 F371	KS62	LP26	KG131	KF25 STD	KJ09B	KJ10	#11	5.5
861B006-4	4	E589	(D390) D675+D969	H974	1.6	P975 F380	BK03	LP26	KG131	KF25 STD	KJ11B	KJ10	#11	5.5
861B003-4	4	E784	(D569) D438+D674	H442	1.6	P152 F155		LP26	KG131	KF25 STD	KJ09B	KJ10	#9	5.5
862B023-5	2 5	E810	(D575) / D440+D095	H445	1.6	P253 F374	KS62	LP36	KG142	KF26 Hi	KJ11B	KJ13	#11	6.0
862B028-5	2 5	E810A	(D577) D441+D095	H446	2.5	P253 F374	KS62	LP36A	KG142	KF26 Hi	KJ11B	KJ12	#16	6.0
862B021-4	2 4	E809	(D575) D440+D095	H445	1.6	P253 F374	KS62	LP26	KG142	KF26 Hi	KJ11B	KJ13	#11	6.0
862B021-5	2 5	E810	(D575) D440+D095	H445	1.6	P253 F374	KS62	LP26	KG142	KF26 Hi	KJ11B	KJ13	#11	6.0
862B022-3	2 3	E591	(D390) D675+D969	H974	1.6	P975 F381	BK03	LP26	KG142	KF26 Hi	KJ11B	KJ12	#11	6.0
862B024-3	2 3	E804A	(D576) D441+D674	H446	2.5	P230 F503	KS62	LP26A	KG142	KF26 Hi	KJ11B	KJ12	#16	6.0
872B061-4	2 4	E834	(D579) D487+D060	H492	1.6	P500 P501	KS42	LP26	KG153	KF26 STD	KJ11B	KJ10	#14	5.5
872B063-5	3 5	E839	(D581) D489+D502	H497 H500	1.6	P504 P502	KS42	LP26	KG153 KG155	KF26 Hi	KJ11B	KJ12	#14	6.0

Handwritten signature/initials

872B065-6	5 6	E868	(D582) D490+D502	H501	2.5	P502	KS47	LP26	(LP23)	KG155	KF26 HI	KJ11B	KJ12	#18	6.0	
872B069-5	3 5	E982	(D002) D008+D502	H957	1.6	P508 P509	KS42B	LP26	(LP23)	KG153 KG155	KF25 IGA STD	KJ11B	KJ10	#14	5.5	
872B087-6	5 6	E868	(D582) D490+D502	H501	2.5	P955	KS47	LP38	(LP23)	KG155	KF26 HI	KJ11B	KJ12	#18	6.0	
873B381-4 873B581-4	32 4 52 4	E989 E988	(D581) D489+D502	H497 H500	1.6	P233 P255	KS42	LP26	(LP21) (LP23)	KG333 KG355	KF25 STD	KJ11B	KJ10	#11x2 #14x1	6.0	