

MACHINE PARTS CHART **for** **SINGER***



591 V200


591 V300

machine de base

SINGER*

591 V200/300





STITCH LENGTH	ASS
7 S.P.I.	
9 S.P.I.	
10 S.P.I.	
11 S.P.I.	
12 S.P.I.	

