

TITAN DK 2200
FRINGING MACHINE




Fig:3

THREADING DIAGRAM.




Fig: 1





Fig: 2


TITAN DK 2200

TITAN DK 2200NC

A.DE KONINCK
AVENUE SLEECKX 84
B-1030 BRUXELLES



- To change uncut fringes into cut fringes an Allen key of 2,5 mm must be introduced in the clearance hole A (see drawing)
- The key must be introduced until contact with the screw is made, turn the key counter clockwise until a slight resistance is noticed.
WARNING : effort provided on the key must remain very gentle.
- When this has been done, the knife must be fitted to the machine according to the drawing.



TITAN 2200 NC
FRINGING MACHINE
STANDARD PARTS FOR CUT &
UNCUT FRINGES FROM 6cm TO 10cm





Fig : 13



TITAN DK 2200

Fig:14




Fig : 16





Fig : 17





Fig:18



TITAN DK 2200

Fig: 19

Fig:20





Fig:21




Fig:22

TITAN DK 2200




Fig: 24

Fig:23


FRINGING MACHINE

WARNING :Never make fringes without carpet under the presser foot

TITAN DK 2200

WARNING :When two carpets are following one another any space between them is to avoid

Fringe puller and hook bar mechanism.



DK 2200: FRINGES BLOWER.

3221 4115

chapa de agulha nº 22148

loop nº 22666

quica de agulha 22151

dente 22401

quica da ~~agulha~~ ^{chapa} 22153-

Parte do quica da chapa parte de uma 22152


suporte do gancho 22110

nó do calador 22223-

Base do calador 22223A

Agulhas 7742 nº330

Standard parts for fringe length, from 6 to 10 cm.



DK 2200 : FRINGES BLOWER.