


SINGER**



167W100







THE SINGER MANUFACTURING COMPANY



17837-3/8

17850-1/4










265700- $\frac{1}{4}$ - $\frac{9}{32}$ - $\frac{5}{16}$ - $\frac{11}{32}$

265702- $\frac{3}{8}$ - $\frac{13}{32}$ - $\frac{7}{16}$

265704- $\frac{15}{32}$ - $\frac{1}{2}$ - $\frac{17}{32}$

202923




265706- $\frac{9}{16}$ - $\frac{19}{32}$ - $\frac{5}{8}$

265708- $\frac{21}{32}$ - $\frac{11}{16}$ - $\frac{23}{32}$

265710- $\frac{3}{4}$ - $\frac{25}{32}$ - $\frac{13}{16}$


202923




265712- $\frac{27}{32}$ - $\frac{7}{8}$ - $\frac{29}{32}$

265714- $\frac{15}{16}$ - $\frac{31}{32}$ -1


202923




267269
 $\frac{1}{4}$ to $\frac{15}{32}$
In Steps of $\frac{1}{32}$ Inch




267270
 $\frac{1}{2}$ to $\frac{3}{4}$
In Steps of $\frac{1}{32}$ Inch




267271
 $\frac{25}{32}$ to 1
In Steps of $\frac{1}{32}$ Inch






19114 - 5/8




19113 - 5/8



265731-1/4-9/32
 265739-5/16-11/32
 265732-3/8-13/32-7/16
 265733-15/32-1/2-17/32

265734-9/16-19/32-5/8
 265735-21/32-11/16-23/32
 265736-3/4-25/32-13/16


265737-27/32-7/8-29/32
 265738-15/16-31/32-1






265621
 265622
 265623



265624
 265625
 265626



265627
 265628



41400



225554



225486



240566




10875



225498



228476



120342

120343

